


	2810 Sydney Road Plant City, Florida 33566 Phone: 813-305-1415 Fax: 813-305-1419
	PLAN AND SECTION 5 ROW BLEACHER TID IN IDALI
	NR-05I5AS-TR AND NR-05I5GS-TR
ATTACH TREATED WOOD SILL TO BOTTOM FRAME RUNNER USING 3/8" x I-I/4" LAG SCREW WITH FLAT WASHER	DRAWN BY CHECKED BY DATE APRIL 2010 SCALE NOTED JOB NO. NR-0515AS- NR-0515GS- DWG NO.
MUD SILL ATTACHMENT	1 OF 2



2810 Sydney Road 2810 Sydney Road Plant City, Florida 33566 Phone: 813-305-1415 Fax: 813-305-1419 A PLAYCOTE Commun WWW. gtgrandstands.com
DETAILS 5 ROW BLEACHER TIP - N - ROLL
NR-05xxAS-TR AND NR-05xxGS-TR
DRAWN BY CHECKED BY DATE APRIL 2010 SCALE NOTED JOB NO. NR-05XXAS-TR NR-05XXGS-TR DWG NO. 2 OF 2